



MAX SHINE

Next Generation Floor Finish

DESCRIPTION

Max Shine is a revolutionary, new-technology floor finish designed to save time and money. **Max Shine** is a combination of urethane and polymers that deliver a rich, water clear gloss to bring out a floor's natural beauty without hiding under a thick, wax barrier.

Max Shine's unique chemistry enables it to be applied in thin coats: up to 4000 square feet per US gallon, nearly twice its competitors. It can also be walked through while still wet and yet it will not leave footprints.

Max Shine is a cherry-scented, versatile floor finish that can be applied on a variety of floors such as linoleum, marmoleum, vinyl, vinyl asbestos, tile, marble, concrete and even sealed wood. It can be used alone or in conjunction with a high-quality sealer such as *Holdout®*, and can be applied directly on top of most other finishes. **Max Shine** readily responds to high speed burnishing, however some users simply top coat with a thin layer of **Max Shine** to forgo burnishing. **Max Shine** is an extremely durable product that resists chemical attacks, black heel marks and yellowing. It can withstand high traffic wear and the abrasiveness of high speed burnishing equipment so your floor shines bright and clear for a long, long time.

DIRECTIONS

Preparation:

Strip the floor with *#1 Remover* then pick up spent solution with a mop or wet-vac making sure solution does not dry. Rinse floor with *NeutraMax* as per label instructions.

Application:

1. Use a clean finish mop, either fine string or candy striped. Pre-wet with water and wring out mop to conserve finish. 2. Apply 2-3 even coats of **Max Shine**. More may be required if you have an un-sealed, porous floor or need a good base to propane burnish. 3. Immerse mop in finish. Do not wring your mop but press firmly into wringer to remove excess finish.

Maintenance:

1. Dust floor with treated dust mop. 2. Clean floor by damp mopping or autoscrubber using M-chem's neutral detergent, *NeutraMax*, as per label instructions. 3. Spray buff with *Armor-Ace* or burnish as desired. *Armor-Ace* may be used to enhance the gloss by applying before burnishing. Or use a thin topcoat of **Max Shine** as necessary to restore your floor to its original, glossy shine.

Burnishing:

Those who burnish **Max Shine** generally use a medium synthetic pad - either champagne or aqua.

PHYSICAL DATA

Solids	20%
Drying Time	5 - 7 minutes (ideal conditions)
Coverage	4000 square feet per US gallon (maximum)
Slip Resistance	Passes ASTM D2047
Performance	Excellent Leveling, Scrubability, Black Mark Resistance and Removability